National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 05/09/1995

MIA95LA040A

File No. 1120		2/15/1994	MEMPHIS, TN	Aircraft Reg No. N927FE		Time (Local): 04:28 CST	
Engine Ma Aircrat Number o Operating Ce Name Type of Flight	lake/Model: ift Damage: of Engines: ertificate(s): of Carrier: Operation:		10	Crew Pass	Fatal 0 0	Serious 0 0	Minor/None 1 0
Last Depart. Point: Same as Accident/Incident Location Destination: DESTIN , FL Airport Proximity: On Airport Airport Name: MEMPHIS INTERNATIONAL Runway Identification: 18L Runway Length/Width (Ft): Unk/Nr Runway Surface: Runway Surface Condition:			Condition of Light: Night/Dark Weather Info Src: Weather Observation Facility Basic Weather: Visual Conditions Lowest Ceiling: 3100 Ft. AGL, Broken Visibility: 8.00 SM Wind Dir/Speed: 140 / 010 Kts Temperature (°C): 7 Obstr to Vision: None Precipitation: None				
Pilot-in-Command Certificate(s)/Rating(s) Flight Instructor; Comm Instrument Ratings Airplane	ificate(s)/Rating(s) Flight Instructor; Commercial; Multi-engine Land; Single-engine Land ument Ratings			Flight Time (Hours) Total All Aircraft: 4900 Last 90 Days: Unk/Nr Total Make/Model: 3600 Total Instrument Time: 800			

THE PILOT OF CESSNA 208, N927FE, STATED THAT AS HE TAXIED TO RUNWAY 18L HE DID NOT SEE ANY AIRCRAFT EXCEPT AN AIRCRAFT WHICH WAS AT THE HOLD SHORT LINE. HE THEN NOTICED THE SILHOUETTE OF DOUGLAS DC3, N24320, AHEAD OF HIM BUT WAS UNABLE TO STOP PRIOR TO COLLIDING WITH THE AIRCRAFT. HE STATED THE TAIL NAVIGATION LIGHTS AND BEACON LIGHTS ON THE DC3 WERE NOT OPERATING. HE ALSO STATED THE TAXIWAY WAS WET AND THERE WAS A GLARE FROM LIGHTS ON A NEARBY RAMP. POSTCRASH EXAMINATION OF DC3 BY FAA INSPECTORS INDICATED THE TAIL NAVIGATION AND BEACON LIGHTS WERE INOPERATIVE.

Brief of Accident (Continued)

MIA95LA040A

File No. 1120 12/15/1994 MEMPHIS, TN Aircraft Reg No. N927FE Time (Local): 04:28 CST

Occurrence #1: COLLISION BETWEEN AIRCRAFT (OTHER THAN MIDAIR)

Phase of Operation: TAXI - TO TAKEOFF

Findings

1. (F) LIGHT CONDITION - DARK NIGHT

2. (C) EXTERIOR LIGHT(S) - INOPERATIVE

3. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT OF OTHER AIRCRAFT

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

THE INABILITY OF THE PILOT OF CESSNA 208, N927FE TO SEE DOUGLAS DC3, N24320, AS HE TAXIED TO TAKEOFF DUE TO INOPERATIVE TAIL NAVIGATION LIGHTS AND BEACON LIGHTS ON THE DC3 AND DUE TO GLARE ON THE WET TAXIWAY.